

DMO TETRA Interoperability Certificate

Sepura, SC2020, DMO Terminal

Cambridge, February 2017

Latest Certified DM Terminal SW Release:	1738 001 08522
Latest Certified DM Terminal HW Release:	TP01STW

ISCTI (Istituto Superiore delle Comunicazioni e delle Tecnologie dell'Informazione) certifies that the Sepura SC2020, DM Terminal has been subject to interoperability testing for the features DMO Core and DMO Air Interface Encryption listed in the "Certified features" tables of this certificate with the following DM Terminals Sepura , SC2020, Sepura STP9000 and Sepura SRG3900 in accordance with the TETRA Interoperability Profiles, TIP compliance Test Plan and related TETRA interoperability requirement tables.

The certificate features associated to each DM terminal are shown in the "Certificate features" tables.


The table lists all the available TETRA interoperability profiles, and summarizes the main functionalities of every profile according to the TETRA interoperability requirement tables.

A feature is "Certified" when it has been successfully tested during the last test session with one of the testing method described in the TETRA process document part 1 (TPD001-01).

A breakdown into the feature details is given in the Feature Compliance Overview section of this certificate.

This certificate has been issued following a fully witnessed single test session on February 2017. Detailed test results are listed in the Test Report associated to this Certificate. Details and explanation about the procedure used to provide verdicts are in the TIC process TPD001-01.

IOP test engineer


Massimo Proietti

Head of the Procedure


Ivano Luciani

Radio Office Manager

Giuseppe Pierri


ISCTI - V.le America 201, 00144 Rome, Italy
Ph.: +39 06 5444 2135, Fax: +39 06 5410904
e-mail: tetra_ctc.iscom@mise.gov.it
Web: www.mise.gov.it

Date of issue:
10 March 2017
v 1

Certified feature

DMO Core Test Session Cambridge, February 2017 Sepura SC2020	Sepura SC2020	Sepura STP9000	Sepura SRG3900
Registration	Certified	Certified	Certified
Group Call	Partial	Certified	Partial
Individual Call	Partial	Partial	Partial
Status Call	-	Certified	-
SDS TL	-	Certified	-
DMO AIE Encryption	Partial	Partial	Partial

Feature Compliance Overview

The first pages of this certificate provide an indication about the main interoperable TETRA features for each TIP specification (as described in the TIC-RT). The main interoperable TETRA features result depend on a set of sub-features, the verdicts associated to each sub-feature are directly derived from the analysis of the performed test cases.

The results associated to each feature and sub-feature are shown in the "Feature compliance report" table below. The main features are indicated with blue background and the associated sub-features (or second level features) have white background.

The outcome assigned to a feature as shown on page 2, is derived by the Feature compliance report tables.

Outcome	Definition
Certified	All required tests have been performed and passed.
Partial	Not all the required test cases have been performed, but none have failed.
-	Feature cannot be certified e.g. it is not supported by at least one product, no tests were performed, or some tests were performed but at least one failed.

The outcome is derived from the verdict assigned to a sub-feature is the result of the analysis of the test case results listed in the Test Report. The verdict assigned to each sub-feature is derived from one or several test case results or test steps result, the TETRA Interoperability requirement tables (TIC-RTs) indicate the link between sub-features and test cases for the certified set of equipment capabilities (see Test Report).

Verdict	Definition
Passed	All mandated tests or steps of tests linked to this functionality (as per TIC-RT indication) are compliant with the TIP specification relevant to this feature or sub-feature.
Incomplete	Not all Mandated tests (as per TIC-RT indication) have been executed.
Failed	At least one of mandated test or steps of tests linked to this functionality failed to match the TIP specification relevant to this feature or sub-feature.

The verdict associated to the feature or sub-feature gives also indication about the method used to test that feature or sub-feature. The allowed testing Methods are listed in the table below, a complete description of the procedures and constraints associated to each of them can be found in the "TPD001-01 TETRA Interoperability Certification Process Description" document.

Testing Method	Description
Complete	All mandated tests associated to the feature or sub-feature have been executed.
Spot	Only a selection of the mandatory test cases associated to the feature or sub-feature has been executed during the test session. These tests are a subset of the tests performed on an equivalent software which has been "completely" tested against the same functionality on a different equipment, see manufacturer declaration in the associated Test Report.
Regression	Only a selection of the mandatory the test cases associated to the feature or sub-feature has been executed during the test session. These tests are a subset of the tests performed on a previous version of the same software which has been "completely" tested in a previous test session against the same functionality, see manufacturer definition in the associated Test Report
Regression on spot	The regression method has been applied on the verdicts based on the spot testing method.
Witnessed	The TIP heading lines in the Feature Compliance Report indicate whether each TIP is partially or fully witnessed by the Certification Body. Additionally, for a partially-witnessed TIP, the number of witnessed test cases that passed is shown for each the feature and sub-feature. There may have been some un-witnessed passed tests and they will have been found to be successful based on the log file evaluation.

Depending on equipment capabilities declared by the manufacturer, some features or sub-feature cannot be tested. The following table describes meaning of the used abbreviation:

Indication	Definition
Not supported	At least one MS do not support the minimum features required to verify these items

ISCTI has made every effort to ensure that every result have been correctly evaluated in accordance with the relevant TIPs, Test Plans and TIC-RTs. ISCTI has no liability for the test results, or towards the manufacturers. The table on the following page lists HW and SW releases of DM Terminals under test in the test session and the used TIP specifications, Test Plans, and TIC-RTs.

This Certificate and Certificates from previous test sessions are available on the TETRA + [Critical Communications Association](https://tandcca.com/interoperability/interoperability-certificates-and-test-reports/) web site (https://tandcca.com/interoperability/interoperability-certificates-and-test-reports/).The feature results are shown in the tables below.

Information on equipment under test and document references

Test Session Place/Date	Cambridge, February 2017
DM Terminal Type	Sepura SC2020
DM Terminal HW release	TP01STW
DM Terminal SW release	1738 001 08522
DM Terminal 1 Type	Sepura SC2020
DM Terminal 1 HW release	TP01STW
DM Terminal 1 SW release	1738 001 08522
DM Terminal 2 Type	Sepura STP9000
DM Terminal 2 HW release	PSYTW201T30WN00
DM Terminal 2 SW release	1738 001 02937
DM Terminal 3 Type	Sepura SRG3900
DM Terminal 3 HW release	MSUTW201T2COG00
DM Terminal 3 SW release	1738 001 03577

TIP Specs and TIP Compliance Test Plans	
DCore	TTR 002-01 v211 IOP 002-01 v103 TIC-RT002-01 v128
DAIE-Core	TTR 002-05 v100 IOP 002-05 v100 TIC-RT002-05-1 v108

Feature compliance report

DMO Test Session Cambridge, February 2017 Sepura SC2020	Sepura SC2020	Sepura STP9000	Sepura SRG3900
TTR002-01 Core – fully witnessed testing			
Registration	PASSED Complete 2_pass_of_2	PASSED Complete 2_pass_of_2	PASSED Complete 2_pass_of_2
Activation/Deactivation	PASSED Complete 1_pass_of_1	PASSED Complete 1_pass_of_1	PASSED Complete 1_pass_of_1
RF Carrier Selection	PASSED Complete 1_pass_of_1	PASSED Complete 1_pass_of_1	PASSED Complete 1_pass_of_1
Group Call	Incomplete 3_pass_of_43	PASSED Complete 43_pass_of_43	Incomplete 3_pass_of_43
Intra-MNI Group Calls	Incomplete 0_pass_of_6	PASSED Complete 6_pass_of_6	Incomplete 0_pass_of_6
Inter-MNI Group Calls	Incomplete 0_pass_of_4	PASSED Complete 4_pass_of_4	Incomplete 0_pass_of_4
Emergency Group Calls	Incomplete 0_pass_of_6	PASSED Complete 6_pass_of_6	Incomplete 0_pass_of_6
Pre-emptive priority Calls	Incomplete 0_pass_of_4	PASSED Complete 4_pass_of_4	Incomplete 0_pass_of_4
Group Call Maintenance	Incomplete 3_pass_of_19	PASSED Complete 19_pass_of_19	Incomplete 3_pass_of_19
Late Entry Group Calls	Incomplete 0_pass_of_4	PASSED Complete 4_pass_of_4	Incomplete 0_pass_of_4
Open Group Calls	Incomplete 0_pass_of_6	PASSED Complete 6_pass_of_6	Incomplete 0_pass_of_6
Individual Call	Incomplete 2_pass_of_20	Incomplete 8_pass_of_20	Incomplete 2_pass_of_20
Intra-MNI Individual Calls	Incomplete 0_pass_of_4	Incomplete 0_pass_of_4	Incomplete 0_pass_of_4
Inter-MNI Individual Calls	Incomplete 0_pass_of_6	Incomplete 2_pass_of_6	Incomplete 0_pass_of_6
Pre-emptive priority Calls	Incomplete 0_pass_of_6	Incomplete 4_pass_of_6	Incomplete 0_pass_of_6

DMO Test Session Cambridge, February 2017 Sepura SC2020	Sepura SC2020	Sepura STP9000	Sepura SRG3900
Individual Call maintenance	Incomplete 2_pass_of_4	Incomplete 2_pass_of_4	Incomplete 2_pass_of_4
Individual Call with Presence Check	Incomplete 2_pass_of_8	PASSED Complete 8_pass_of_8	Incomplete 2_pass_of_8
Individual call without Presence Check	Incomplete 0_pass_of_8	Incomplete 0_pass_of_8	Incomplete 0_pass_of_8
Individual Late Entry	Incomplete 0_pass_of_4	Incomplete 0_pass_of_4	Incomplete 0_pass_of_4
Status Call	Incomplete 0_pass_of_16	PASSED Complete 16_pass_of_16	Incomplete 0_pass_of_16
Individual Status Calls	Incomplete 0_pass_of_2	PASSED Complete 2_pass_of_2	Incomplete 0_pass_of_2
Group Status call	Incomplete 0_pass_of_12	PASSED Complete 12_pass_of_12	Incomplete 0_pass_of_12
Status sent in a Voice Call	Incomplete 0_pass_of_6	PASSED Complete 6_pass_of_6	Incomplete 0_pass_of_6
Status sent out of a Call	Incomplete 0_pass_of_8	PASSED Complete 8_pass_of_8	Incomplete 0_pass_of_8
SDS TL	Incomplete 0_pass_of_8	PASSED Complete 8_pass_of_8	Incomplete 0_pass_of_8
Individual intra-MNI SDS-TL, unacknowledged, 8 bit	Incomplete 0_pass_of_2	PASSED Complete 2_pass_of_2	Incomplete 0_pass_of_2
Individual inter-MNI SDS-TL, unacknowledged, 8 bit	Incomplete 0_pass_of_2	PASSED Complete 2_pass_of_2	Incomplete 0_pass_of_2
Group SDS-TL intra-MNI, unacknowledged, no reports, 8 bit	Incomplete 0_pass_of_2	PASSED Complete 2_pass_of_2	Incomplete 0_pass_of_2
Open TSI addressed SDS-TL, unacknowledged, no reports, 8 bit	Incomplete 0_pass_of_2	PASSED Complete 2_pass_of_2	Incomplete 0_pass_of_2
Multipart SDS-TL	Not_Supported	Not_Supported	Not_Supported

DMO Test Session Cambridge, February 2017 Sepura SC2020	Sepura SC2020	Sepura STP9000	Sepura SRG3900
DMO AIE Encryption	Incomplete 2_pass_of_20	Incomplete 18_pass_of_20	Incomplete 2_pass_of_20
Encrypted Group Calls	Incomplete 0_pass_of_8	PASSED Complete 8_pass_of_8	Incomplete 0_pass_of_8
Encrypted Individual Calls	Incomplete 0_pass_of_4	Incomplete 2_pass_of_4	Incomplete 0_pass_of_4
Encrypted Status messages	Incomplete 0_pass_of_2	PASSED Complete 2_pass_of_2	Incomplete 0_pass_of_2
Pre-emption of encrypted activity	Incomplete 0_pass_of_2	PASSED Complete 2_pass_of_2	Incomplete 0_pass_of_2
Handling mismatched keys	Incomplete 2_pass_of_4	PASSED Complete 4_pass_of_4	Incomplete 2_pass_of_4